CONSTRUCTION EQUIPMENT X58455 VOLVO EC300EL 316607 - REAR LEFT FINAL DRIVE

 Sample No:
 VCP406518

 Oil Type:
 NOT GIVEN

 Job No:
 X58455

VOLVO

| ļ |
|---|
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |



SCOTT EQUIPMENT COMPANY LLC - Saint Rose PO BOX 997 SAINT ROSE, LA US 70087 Contact: DENISE CORVERS

Contact: DENISE CORVERS dcorvers@scottcompanies.com T: (504)461-0961 F: (504)461-0970

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:SCOSAIUnique No:10647712Signed:Wes DavisReport Date:19 Sep 2023

4

<1

ppm

ppm

Barium


Boron

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: SCOSAI [WUSCAR] 05951753 (Generated: 09/20/2023 05:55:50) Rev: 1

Contact/Location: DENISE CORVERS - SCOSAI