

## CONSTRUCTION EQUIPMENT BERGMANN C815S 5704 - FRONT AXLE



Sample No: VCP416382

Oil Type: VOLVO WET BRAKE TRANSAXLE OIL

Job No:

SAMPLE	INFORMATION				
Sample Number		VCP416382			
Sample Date		08 Sep 2023			
Machine Hours		1472			
Oil Hours		0			
Oil Changed		Not Changd			
Sample Status		ABNORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	<b>54.6</b>			
VOLVO	INATION .				
CONTAM	MATIUN				
Silicon	ppm	<b>1</b> 3			
Sodium	ppm	<b>18</b>			
Potassium	ppm	<b>■&lt;1</b>			
VOLVO					
WEAR M	ETALS				
Iron	ppm	■210			
Copper	ppm	<u> </u>			
Lead	ppm	<b>■</b> 2			
Tin	ppm	<b>■</b> 4			
Aluminum	ppm	■2			
Chromium	ppm	<b>■</b> 2			
Molybdenum	ppm	<b>□</b> 7			
Nickel	ppm	<b>■</b> 6			
Titanium	ppm	<1			
Silver	ppm	0			
Manganese	ppm	55			
Vanadium	ppm	<1			
VOLVO					
ADDITIV	ES				
Calcium	ppm	■3428			
ADDITIV		□ 3428 □ <1			
Calcium	ppm	_			
Calcium Magnesium	ppm ppm	<u> </u>			
Calcium Magnesium Zinc	ppm ppm ppm	□<1 □1436			



## ALTA EQUIPMENT COMPANY 5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: DEWAYNE BEARD DBeard@flaglerce.com T: (239)481-8554

## Diagnosis

F: (239)481-3302

No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VOLVO0090

 Unique No:
 10655625

 Signed:
 Sean Felton

 Report Date:
 20 Sep 2023



## **CONSTRUCTION EQUIPMENT**





