



CONSTRUCTION EQUIPMENT

VOLVO NOT GIVEN 310908 - FRONT LEFT DRIVE



Sample No: VCP401169
Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5
Job No:



SAMPLE INFORMATION

Sample Number	VCP401169	---	---	---
Sample Date	16 Sep 2023	---	---	---
Machine Hours	6553	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	SEVERE	---	---	---

ALTA EQUIPMENT COMPANY
 5151 DR MARTIN LUTHER KING BLVD
 FORT MYERS, FL
 US 33905
 Contact: TODD LARK
 tlark@altaequipfl.com
 T:
 F: (239)481-3302



OIL CONDITION

Visc @ 40°C	cSt	■ 328	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	● 2.30	---	---	---
Silicon	ppm	● 2169	---	---	---
Sodium	ppm	■ 20	---	---	---
Potassium	ppm	■ 19	---	---	---



WEAR METALS

Iron	ppm	● 5754	---	---	---
Copper	ppm	■ 9	---	---	---
Lead	ppm	■ 2	---	---	---
Tin	ppm	■ 2	---	---	---
Aluminum	ppm	▲ 98	---	---	---
Chromium	ppm	● 33	---	---	---
Molybdenum	ppm	■ 4	---	---	---
Nickel	ppm	● 19	---	---	---
Titanium	ppm	10	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 35	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	■ 1274	---	---	---
Magnesium	ppm	■ 48	---	---	---
Zinc	ppm	■ 38	---	---	---
Phosphorus	ppm	■ 955	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 217	---	---	---

Diagnosis

We advise that you check all areas where dirt can enter the system. We advise that you check for the source of water entry. The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. Gear wear is indicated. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. There is a high concentration of water present in the oil. The oil is no longer serviceable due to the presence of contaminants.

Depot: VOLVO0090
Unique No: 10657953
Signed: Jonathan Hester
Report Date: 22 Sep 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

