

CONSTRUCTION EQUIPMENT PUMP 2 - PUMP



Sample No: VCP326067
Oil Type: NOT GIVEN

Job No:

INFORMATION				
-	VCP326067	VCP326065	VCP386939	
	25 Sep 2023	05 Sep 2023	27 Aug 2023	
	0	0	0	
	0	0	0	
	N/A	N/A	N/A	
	NORMAL	NORMAL	NORMAL	
DITION				
	□ 147	m 148	m 147	
CSC	<u> </u>	<u> </u>	<u> </u>	
MINATION				
ppm	6	■8	7	
ppm	■ 0	0	- <1	
ppm	■ <1	2	0	
METALS				
ppm	■4	4	4	
ppm	■ <1	0	□0	
ppm	0	0	0	
ppm	■ 0	0	0	
ppm	0	- <1	0	
ppm	■0	0	□0	
ppm	0	0	<1	
ppm	<1	0	0	
ppm	0	0	0	
ppm	0	0	0	
ppm	0	0	<1	
ppm	0	0	0	
IES				
ppm	<1	2	2	
ppm	<1	0	0	
ppm	3	0	0	
ppm	116	96	99	
	_		0	
ppm	1	0	0	
	DITION cSt AINATION ppm ppm ppm ppm ppm ppm ppm ppm ppm p	25 Sep 2023	VCP326067 VCP326065 25 Sep 2023 05 Sep 2023 0	VCP326067 VCP326065 VCP386939 25 Sep 2023 05 Sep 2023 27 Aug 2023 0



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0093Unique No:10662062Signed:Sean FeltonReport Date:27 Sep 2023



CONSTRUCTION EQUIPMENT





