Sample No: VCP392581

Oil Type: CHEVRON 15W40

Job No: MARTIN MARIETTA

VOLVO	INFORMATION			
	. INFURMATION			
Sample Number		VCP392581	VCP411273	
Sample Date		03 Aug 2023	09 Mar 2023	
Machine Hours		2004	1029	
Oil Hours		0	0	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	MARGINAL	
OIL CON	DITION			
Visc @ 40°C	cSt	76.1	76.8	
		_	_	
VOLVO	AINIS TION			
LUNIAN	MINATION			
Silicon	ppm	■8	1 2	
Sodium	ppm	2	6	
Potassium	ppm	2	0	
WEAR N	METALS			
Iron	ppm	18	1 0	
Copper	ppm	■8	1 5	
Lead	ppm	■<1	0	
Tin	ppm	■0	<1	
Aluminum	ppm	■3	2	
Chromium	ppm	■0	□ <1	
Molybdenum	ppm	■ 102	1 42	
Nickel	ppm	0	0	
Titanium	ppm	<1	<1	
Silver	ppm	64	71	
Manganese	ppm	■<1	2	
Vanadium	ppm	0	<1	
	77			
VOLVO				
ADDITIV	/ES			
Calcium	ppm	1470	1638	
Magnesium	ppm	584	529	
Zinc	ppm	951	■1057	
Phosphorus	ppm	795	■941	
Barium	ppm	■0	0	
Boron	ppm	278	1 72	

ROMCO INC - AUSTIN BRANCH

1150 WEST OLD SETTLERS BOULEVARD ROUNDROCK, TX US 78681 Contact: ED MAYES EMAYES@ROMCO.COM T: (737)204-9402 F: (512)388-2673

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO0088Unique No:10669702Signed:Don BaldridgeReport Date:29 Sep 2023



CONSTRUCTION EQUIPMENT





