

## CONSTRUCTION EQUIPMENT VOLVO L70H 624874 - TRANSMISSION (AUTO)



TALAT

## Sample No: VCP376063

VOLVO AUTOMATIC TRANSMISSION FLUID AT102

## Oil Type: Job No:

SAMPLE INFORMATION						
		<u>.</u>		<u>.</u>		
Sample Number		VCP376063				
Sample Date		27 Sep 2023				ALTA EQUIPMENT COMPANY
Machine Hours		2008				5151 DR MARTIN LUTHER KING BLVD
Oil Hours		0				FORT MYERS, FL
Oil Changed		Not Changd				US 33905
Sample Status		ABNORMAL				Contact: TODD LARK
						tlark@altaequipfl.com
OIL CON	IDITION					T:
Visc @ 40°C	cSt					F: (239)481-3302
VISC @ 40 C	CSL	29.0				
VOLVO						Diagnosis
CONTA	MINATION					No corrective action is recommended
Silicon	ppm	11				at this time. Resample at the next service interval to monitor.The iron
Sodium	ppm	3				
Potassium	ppm	3				level is abnormal. All other
	1.1.					component wear rates are normal.
VOLVO						There is no indication of any
WEAR METALS						contamination in the fluid. The
Iron	ppm	<u> </u>				condition of the fluid is acceptable for the time in service.
Copper	ppm	8				for the time in service.
Lead	ppm	0				
Tin	ppm	0				
Aluminum	ppm	2				
Chromium	ppm	<b>■</b> <1				
Molybdenum	ppm	3				
Nickel	ppm	<b></b> <1				
Titanium	ppm	0				
Silver	ppm	0				
Manganese	ppm	9				
Vanadium	ppm	0				
	VES					
Calcium	ppm	148				
Magnesium	ppm	30				
Zinc	ppm	93				
Phosphorus	ppm	237				
Barium	ppm	0				
Boron		68				
DOTOTI	ppm	00				

 Depot:
 VOLVO0090

 Unique No:
 10672349

 Signed:
 Don Baldridge


 Report Date:
 03 Oct 2023

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO



Page 2 of 2