



# CONSTRUCTION EQUIPMENT

W07013576-1 VOLVO A25G 752339 - WET DISC BRAKE



**Sample No:** VCP409362  
**Oil Type:** VOLVO WB 102  
**Job No:** W07013576-1



**McClung-Logan Virginia LLC- RICHMOND**  
1345 MOUNTAIN ROAD  
GLEN ALLEN, VA  
US 23060  
Contact: KYLE RATLIFFE  
KRATLIFFE@MCCLUNG-LOGAN.COM  
T:  
F: (804)266-1611



## SAMPLE INFORMATION

Sample Number	VCP409362	---	---	---
Sample Date	05 Oct 2023	---	---	---
Machine Hours	2558	---	---	---
Oil Hours	2558	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	ABNORMAL	---	---	---



## OIL CONDITION

Visc @ 40°C	cSt	■ 43.6	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	■ 13	---	---	---
Sodium	ppm	■ <1	---	---	---
Potassium	ppm	■ 4	---	---	---



## WEAR METALS

Iron	ppm	■ 29	---	---	---
Copper	ppm	▲ 199	---	---	---
Lead	ppm	■ <1	---	---	---
Tin	ppm	■ 0	---	---	---
Aluminum	ppm	■ 0	---	---	---
Chromium	ppm	■ 0	---	---	---
Molybdenum	ppm	■ <1	---	---	---
Nickel	ppm	■ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 1	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	■ 3110	---	---	---
Magnesium	ppm	■ 6	---	---	---
Zinc	ppm	■ 1407	---	---	---
Phosphorus	ppm	■ 1220	---	---	---
Barium	ppm	■ 4	---	---	---
Boron	ppm	■ 101	---	---	---

## Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLVO8882  
**Unique No:** 10688088  
**Signed:** Don Baldrige  
**Report Date:** 13 Oct 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

