

Sample No: VCP432706
Oil Type: NOT GIVEN

**Job No:** 45595 IRON SMART

SAMPLE	INFORMATIO	N		
Sample Number	-	VCP432706	 	
Sample Date		10 Oct 2023	 	
Machine Hours		8084	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
		, , , , , , , , , , , , , , , , , , , ,		
OIL CON	DITION			
Visc @ 40°C	cSt	= 20.1		
VISC @ 40°C	CST	<b>28.1</b>	 	
VOLVO				
CONTAN	MINATION			
Silicon	ppm	<b>6</b>	 	
Sodium	ppm	<b>1</b>	 	
Potassium	ppm	<b>2</b>	 	
	pp			
VOLVO				
<b>WEAR</b> N	METALS			
ron	ppm	<b>72</b>	 	
Copper	ppm	<b>■72</b>	 	
Lead	ppm	<b>■&lt;1</b>	 	
Tin	ppm	<b>4</b>	 	
Aluminum	ppm	■8	 	
Chromium	ppm	<b>-&lt;1</b>	 	
Molybdenum	ppm	1	 	
Vickel	ppm	<b>4</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
/anadium	ppm	0	 	
ADDITIV	/ES			
Calcium	ppm	177	 	
Magnesium	ppm	6	 	
Zinc	ppm	75	 	
Phosphorus	ppm	179	 	
Barium	ppm	0	 	
Boron	ррт	30	 	
ווטוטם	ppiii	30		



SCOTT EQUIPMENT COMPANY LLC - Lavergne
1231 BRIDGESTONE PARKWAY
LAVERGNE, TN
US 37086
Contact: BILLY BEARD
jbeard@scottcompanies.com
T:
F: (615)793-9655

## Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO0129Unique No:10695862Signed:Don BaldridgeReport Date:17 Oct 2023



## **CONSTRUCTION EQUIPMENT**





