CONSTRUCTION EQUIPMENT 384881 VOLVO L60H 623294 - FRONT AXLE



 Sample No:
 VCP431761

 Oil Type:
 VOLVO WB 102

 Job No:
 384881

Boron

ppm

VOLVO

	E INFORMATION				
Sample Number		VCP431761		 	
Sample Date		11 Oct 2023		 	R
Machine Hours		1079		 	12
Oil Hours		1079		 	0
Oil Changed		Not Changd		 	U:
Sample Status		NORMAL		 	Co
Sample Status		NORMAL		 	
VOLVO					T:
VIL CON	DITION				F:
Visc @ 40°C	cSt	41.8		 	
VOLVO CONTA	MINATION				D
		·	<u>.</u> .		R
Silicon	ppm	1 6		 	te
Sodium	ppm	2		 	а
Potassium	ppm	3		 	a
VOLVO					c t
WEAR	METALS				
Iron	ppm	74		 	
Copper	ppm			 	
Lead	ppm	0		 	
Tin	ppm	0		 	
Aluminum	ppm	1		 	
Chromium	ppm	4		 	
Molybdenum	ppm	□ <1		 	
Nickel	ppm			 	
Titanium	ppm	<1		 	
Silver	ppm	0		 	
Manganese	ppm	7		 	
Vanadium	ppm	0		 	
VOLVO					
ADDITI	VES				
Calcium	ppm	4024		 	
Magnesium	ppm	8		 	
Zinc	ppm	1712		 	
Phosphorus	ppm	1284		 	
Barium	ppm	0		 	



RECYCLE AMERICA

12100 YOUNG PINE RD ORLANDO, FL JS 32829 Contact: SERVICE MANAGER

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	RECORL	
Unique No:	10697312	
Signed:	Wes Davis	
Report Date:	17 Oct 2023	


129

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: RECORL [WUSCAR] 05980017 (Generated: 10/27/2023 06:08:55) Rev: 1

Contact/Location: SERVICE MANAGER ? - RECORL