

## CONSTRUCTION EQUIPMENT VOLVO A40G 352682 - DROP BOX



Sample No: VCP407337
Oil Type: NOT GIVEN

Job No:

FORMATION				
	VCP407337			
	27 Sep 2023			
	2121			
	0			
	N/A			
	ABNORMAL			
ION				
cSt	<b>48.8</b>			
ATION				
ATIUN				
ppm				
ppm				
ppm	<b>6</b>			
ALS				
ppm	<b>136</b>			
ppm	_			
ppm	_			
ppm				
ppm	<b>■</b> <1			
ppm	_			
ppm				
•				
ppm				
ppm				
ppm	0			
ppm	29			
ppm	0			
ppm	128			
ppm	2110			
ppm	0			
	ppm	VCP407337	VCP407337 27 Sep 2023 2121 0	VCP407337



LANDMARK CONSTRUCTION CO. INC./MEM 3255 INDUSTRY DRIVE NORTH CHARLESTON, SC US 29418 Contact: GENE RICHARDSON grichardson@landmark-sc.com T: (843)767-9741

## Diagnosis

F: (843)767-9909

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. Elemental level of silicon (Si) above normal indicating ingress of seal material. The condition of the oil is acceptable for the time in service.

Depot:LANNORUnique No:10697333Signed:Don BaldridgeReport Date:18 Oct 2023



## **CONSTRUCTION EQUIPMENT**





