Sample No: VCP443139
Oil Type: VOLVO WB 102

Job No: 19768 LANE BLYTHE

ZAMPI	E INFORMATION				
			VCD 4475C4	VCD207524	
Sample Number		VCP443139	VCP417564	VCP387524	
Sample Date		06 Oct 2023	06 Jun 2023	24 Aug 2022	
Machine Hours		5191	4749	3927	
Oil Hours		0	0	0	
Oil Changed		Not Changd	Not Changd	Changed	
Sample Status		ABNORMAL	ABNORMAL	ABNORMAL	
OIL CON	IDITION				
Visc @ 40°C	cSt	40.8	■ 44.6	■39.4	
VISC @ 40 C	CSt	10.0		□ 55.4	
VOLVO					
CONTAI	MINATION				
Silicon	ppm	21	1 9	2 0	
Sodium	ppm	4	8	<u>8</u>	
Potassium	ppm	■3	0	□0	
	P P				
VOLVO					
WEAR I	METALS				
Iron	ppm	■20	1 9	1 7	
Copper	ppm	^ 265	A 231	△ 301	
Lead	ppm	0	2	3	
Tin	ppm	0	- <1	1	
Aluminum	ppm	2	- <1	3	
Chromium	ppm	<1	- <1	<u></u> <1	
Molybdenum	ppm	<1	<1	<1	
Nickel	ppm	6	6	8	
Titanium	ppm	<1	<1	<1	
Silver	ppm	0	0	<1	
Manganese	ppm	■<1	1	1	
/anadium	ppm	0	<1	0	
Variaciditi	ррпп	V	~ 1	O	
VOLVO					
ADDITI	VES				
Calcium	ppm	■3622	■3616	3439	
Magnesium	ppm	■ 9	9	9	
Zinc	ppm	1557	□ 1518	1466	
Phosphorus	ppm	1312	1287	1207	
Barium	ppm	■<1	1 0	0	
Boron	ppm	109	125	130	
	1.				



117 - ASCENDUM MACHINERY INC - GREENVILLE 2002 N GREENE ST GREENVILLE, NC US 27834 Contact: ALLEN WILLIAMS allen.williams@ascendummachinery.com T:

F: (704)494-8197

Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO8769Unique No:10702430Signed:Don BaldridgeReport Date:23 Oct 2023



CONSTRUCTION EQUIPMENT





