

CONSTRUCTION EQUIPMENT
19708 STRATEGIC MAT VOLVO L90H 625283 - FRONT AXLE

Sample No: VCP435272 Oil Type: VOLVO WB 102

Job No: 19708 STRATEGIC MAT

VOLVO	INFORMATION	N.		
	INFURMATIU			
Sample Number		VCP435272	VCP319256	 
Sample Date		26 Sep 2023	15 Sep 2021	 
Machine Hours		3029	1040	 
Oil Hours		0	0	 
Oil Changed		Not Changd	Changed	 
Sample Status		NORMAL	NORMAL	 
OIL CON	NITION			
		= 42.0	- 40.1	
Visc @ 40°C	cSt	<b>43.0</b>	<b>40.1</b>	 
VOLVO				
CONTAM	IINATION			
Silicon	ppm	<b>1</b> 4	<b>9</b>	 
Sodium	ppm	<b>-</b> <1	8	 
Potassium	ppm	<b>2</b>	<b>1</b> 0	 
T Gtassiani	PPIII			
VOLVO				
WEAR M	IETALS			
Iron	ppm	<b>■</b> 36	■37	 
Copper	ppm	<b>■&lt;1</b>	<b>-</b> <1	 
Lead	ppm	<b>■&lt;1</b>	□0	 
Tin	ppm	<b>■</b> 0	<b>0</b>	 
Aluminum	ppm	<b>2</b>	< 1	 
Chromium	ppm	■1	<b>2</b>	 
Molybdenum	ppm	<b>4</b>	8	 
Nickel	ppm	<b>■&lt;1</b>	<b>0</b>	 
Titanium	ppm	<1	0	 
Silver	ppm	0	<1	 
Manganese	ppm	<b>4</b>	9	 
Vanadium	ppm	0	0	 
ADDITIV	Ι <b>Γ</b> ς			
	_	- 4000	252	
Calcium	ppm	<b>4233</b>	3534	 
Magnesium	ppm	<b>2</b> 4	9	 
Zinc	ppm	<b>1700</b>	1395	 
Phosphorus	ppm	<b>1357</b>	1140	 
Barium	ppm	<b>-</b> <1	0	 
Boron	ppm	<b>144</b>	152	 



117 - ASCENDUM MACHINERY INC - GREENVILLE

2002 N GREENE ST GREENVILLE, NC US 27834

Contact: BRANDON JENKINS BRANDON, JENKINS@ASCENDUMMACHINERY.COM

T:

F: (704)494-8197

## Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO8769 **Unique No:** 10702450 Signed: Wes Davis Report Date: 23 Oct 2023



## **CONSTRUCTION EQUIPMENT**





