

## **CONSTRUCTION EQUIPMENT**

19618 TGP CATERPILLAR 345BL AGSO2135 - REAR RIGHT FINAL DRI

Sample No: VCP414154
Oil Type: NOT GIVEN
Job No: 19618 TGP

SAMPLE	INFORMATION				
Sample Number		VCP414154			
Sample Date		02 Oct 2023			
Machine Hours		14659			
Oil Hours		0			
Oil Changed		Not Changd			
Sample Status		ABNORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	<b>165</b>			
CONTAM	INATION				
_					
Silicon	ppm	<b>48</b>			
Sodium	ppm	<b>0</b>			
Potassium	ppm	<b>■</b> 5			
VOLVO					
WEAR M	ETALS				
Iron	ppm	<b>136</b>			
Copper	ppm	<u> </u>			
Lead	ppm	<b>■</b> <1			
Tin	ppm	<b>■</b> 3			
Aluminum	ppm	<b>16</b>			
Chromium	ppm	<b>4</b>			
Molybdenum	ppm	4			
Nickel	ppm	<b>■</b> <1			
Titanium	ppm	■1			
Silver	ppm	■0			
Manganese	ppm	<1			
Vanadium	ppm	<1			
VOLVO					
ADDITIV	ES				
Calcium	ppm	2566			
Magnesium	ppm	32			
Zinc	ppm	1065			
Phosphorus	ppm	969			
Barium	ppm	<1			
Boron	ppm	8			



117 - ASCENDUM MACHINERY INC - GREENVILLE 2002 N GREENE ST GREENVILLE, NC US 27834 Contact: BRANDON JENKINS BRANDONJENKINS@ASCENDUMMACHINERY.COM T:

F: (704)494-8197

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.Bearing and/or bushing wear is indicated. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO8769Unique No:10702490Signed:Don BaldridgeReport Date:23 Oct 2023



## **CONSTRUCTION EQUIPMENT**





