

CONSTRUCTION EQUIPMENT
375637 WEINTRAB RECY VOLVO EC300 310153 - DIESEL ENGINE

Sample No: VCP429180

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

Job No: 375637 WEINTRAB RECY

N			
VCP429180	VCP376631		
04 Oct 2023	01 Aug 2022		
5303	3343		
0	1500		
Changed	Changed		
NORMAL	NORMAL		
13.3	□13.5		
g 5.0	■8.6		
102	56		
■ 0.2	□0.1		
	04 Oct 2023 5303 0 Changed NORMAL	VCP429180 VCP376631 04 Oct 2023 01 Aug 2022 5303 3343 0 1500 Changed Changed NORMAL NORMAL 13.3 13.5 g 5.0 18.6 102 56	VCP429180 VCP376631 04 Oct 2023 01 Aug 2022 5303 3343 0 1500 Changed Changed NORMAL NORMAL 13.3 13.5 9 5.0 8.6 102 56

CONTAMINATION						
Soot %	%	■0.2	□0.1			
Nitration (PA)	%	103	71			
Sulfation (PA)	%	71	55			
Glycol	%	NEG	NEG			
Fuel	%	<1.0	< 1.0			
Silicon	ppm	■ 9	4			
Sodium	ppm	■3	1			
Potassium	ppm	2	3			

WEAR N	METALS			
Iron	ppm	24	1 1	
Copper	ppm	■ 3	2	
Lead	ppm	■8	< 1	
Tin	ppm	■ 3	- <1	
Aluminum	ppm	4	3	
Chromium	ppm	■<1	- <1	
Molybdenum	ppm	44	2 9	
Nickel	ppm	■<1	0	
Titanium	ppm	<1	<1	
Silver	ppm	■ 0	<1	
Manganese	ppm	■<1	< 1	
Vanadium	ppm	0	0	

VES				
ppm	1977	1711		
ppm	■ 578	437		
ppm	1350	■1057		
ppm	1007	■872		
ppm	■ 0	■0		
ppm	11	■59		
	ppm ppm ppm ppm	ppm	ppm	ppm



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: JOHN FARDELLA john.fardella@altg.com T: (813)630-0077 F: (813)630-2233

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot: VOLVO0093 **Unique No:** 10708821 Signed: Don Baldridge Report Date: 25 Oct 2023



CONSTRUCTION EQUIPMENT





