

# CONSTRUCTION EQUIPMENT SW1025599 VOLVO L120H 633369 - REAR AXLE



 Sample No:
 VCP405403

 Oil Type:
 VOLVO WB 102

 Job No:
 SW1025599

VOLVO CAMPIE	INFORMATION			
	. IINI OMPIATION	VCD 405 403	VCD44.003.4	
Sample Number		VCP405403	VCP416034	 
Sample Date		20 Oct 2023	21 Aug 2023	 
Machine Hours		1954	1436	 
Oil Hours		0	0	 
Oil Changed		Changed	Changed	 
Sample Status		NORMAL	NORMAL	 
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>43.2</b>	<b>42.0</b>	 
COLVO	MINATION			
_	IINA HUN			
Silicon	ppm	<b>14</b>	■28	 
Sodium	ppm	■2	<b>4</b>	 
Potassium	ppm	<b>0</b>	< 1	 
VOLVO				
WEAR N	METALS			
Iron	ppm	<b>■95</b>	□358	 
Copper	ppm	<b>0</b>	<b>-</b> <1	 
Lead	ppm	<b>0</b>	<b>0</b>	 
Tin	ppm	_ <1	0	 
Aluminum	ppm	<1	<b>4</b>	 
Chromium	ppm	<u> </u>	<b>1</b> 6	 
Molybdenum	ppm	<b>4</b>	<b>1</b> 3	 
Nickel	ppm	<1	2	 
Titanium	ppm	<1	<1	 
Silver	ppm	0	0	 
Manganese	ppm	<b>■</b> 3	<b>□</b> 12	 
Vanadium	ppm	0	0	 
	le le	-		
VOLVO	IFC			
<b>ADDITIV</b>	JE2			
Calcium	ppm	■3494	<b>4063</b>	 
Magnesium	ppm	<b>■</b> 0	<b>1</b> 8	 
Zinc	ppm	<b>1388</b>	<b>1608</b>	 
Phosphorus	ppm	<b>1087</b>	■1335	 
Barium	ppm	<b>■</b> 0	□0	 
Boron	ppm	<b>127</b>	<b>144</b>	 



### ARNOLD MACHINERY COMPANY

4323 EAST WINSLOW AVENUE PHOENIX, AZ US 85040 Contact: RANDY PRZEKURAT randyp@arnoldmachinery.com T: F: (602)414-1904

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO6174Unique No:10714509Signed:Wes DavisReport Date:30 Oct 2023



## **CONSTRUCTION EQUIPMENT**





