

Sample No: VCP441697
Oil Type: VOLVO WB 102

**Job No:** W14861

CAMPI	E INFORMATION	N		
Sample Number		VCP441697	 	
Sample Date		27 Oct 2023	 	
Machine Hours		991	 	
Oil Hours		1000	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>41.6</b>	 	
	COC			
VOLVO				
CONTAI	MINATION			
Silicon	ppm	<b>17</b>	 	
Sodium	ppm	<b>7</b>	 	
Potassium	ppm	<b>■&lt;1</b>	 	
WEAR	METALS			
Iron	ppm	<b>10</b>	 	
Copper	ppm	<b>16</b>	 	
Lead	ppm	<b>1</b>	 	
Tin	ppm	<b></b>	 	
Aluminum	ppm	<b>1</b>	 	
Chromium	ppm	<b>■&lt;1</b>	 	
Molybdenum	ppm	<b>0</b>	 	
Nickel	ppm	<b>■</b> 3	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>■&lt;1</b>	 	
Vanadium	ppm	0	 	
ADDITIV	VES			
Calcium	ppm	■3701	 	
Magnesium	ppm	<b>24</b>	 	
Zinc	ppm	<b>1605</b>	 	
Phosphorus	ppm	■1362	 	
Barium	ppm	■0	 	
Boron	ppm	<b>115</b>	 	
	-   - · · ·			



## **HOUSBY HEAVY EQUIPMENT, LLC**

4410 SE 4 MILE DR ANKENY, IA US 50021 Contact: RANDY VANDERLEEST rvanderleest@housby.com T: F: (515)964-2865

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO0080Unique No:10723064Signed:Don BaldridgeReport Date:01 Nov 2023



## **CONSTRUCTION EQUIPMENT**





## GRAPHS

