

## **CONSTRUCTION EQUIPMENT**

443 VOLVO EC950F 410052 - REAR LEFT TRACK DRIVE

Sample No: VCP412890

Oil Type: MOBIL MOBILUBE HD 85W140

**Job No:** 443

VOLVO	INFORMATIO	VI			
	INFUKMATIU			<u> </u>	_
Sample Number		VCP412890			
Sample Date		20 Oct 2023			
Machine Hours		4151			
Oil Hours		0			
Oil Changed		Changed			
Sample Status		ABNORMAL			
VOLVO					
OIL CONE	DITION				
Visc @ 40°C	cSt	<b>282</b>	_		
VISC @ 40 C	CSL	202			
VOLVO					
CONTAM	INATION				
Silicon	ppm	<u>▲</u> 191			
Sodium	ppm	<b>18</b>			
Potassium	ppm	<b>17</b>			
WEAR M	ETALC				
_	E I WF7				
Iron	ppm	<b>428</b>			
Copper	ppm	<b>4</b>			
Lead	ppm	<b>1</b>			
Tin	ppm	<b></b>			
Aluminum	ppm	<u> </u>			
Chromium	ppm	<b>5</b>			
Molybdenum	ppm	<b>0</b>			
Nickel	ppm	<b>1</b>			
Titanium	ppm	2			
Silver	ppm	0			
Manganese	ppm	<b>5</b>			
Vanadium	ppm	<1			
VOLVO					
<b>ADDITIV</b>	ES				
Calcium	ppm	<b>24</b>			
Magnesium	ppm	<b>21</b>			
Zinc	ppm	<b>6</b>			
Phosphorus	ppm	■865			
Barium	ppm	<b>1</b>			
Boron	ppm	<b>70</b>			
	10 10.11				

#### **VCES- VOLVO CONSTRUCTION EQUIPMENT**

12345 MAPLEVIEW STREET LAKESIDE, CA

US 92040

Contact: Mark Stewart mark.stewart@vcesvolvo.com

T: X: F: X:

### Diagnosis

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. Elemental levels of silicon (Si) and aluminum (Al) indicate aluminasilicate (coarse dirt) ingress. The condition of the oil is acceptable for the time in service.

Depot:VOLVO4488Unique No:10723076Signed:Don BaldridgeReport Date:01 Nov 2023



# **CONSTRUCTION EQUIPMENT**





