

CONSTRUCTION EQUIPMENT 443 VOLVO EC950F 410052 - LEFT SWING DRIVE



Sample No: VCP412742

Oil Type: GEAR OIL SAE 85W140

Job No: 443

SAMPLE	E INFORMATION			
Sample Number	-	VCP412742	VCP350212	
Sample Date		20 Oct 2023	05 Jul 2022	
Machine Hours		4151	1180	
Oil Hours		0	1180	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	ABNORMAL	
OIL CON	DITION			
Visc @ 40°C	cSt	341	174	
VISC @ 40 C	CSL	341	174	
VOLVO				
CONTAI	MOITANIN			
Silicon	ppm	■8	1 5	
Sodium	ppm	2	0	
Potassium	ppm	1	1	
WEAR	METALS			
Iron	ppm	105	<u>▲</u> 863	
Copper	ppm	■ 4	1 2	
Lead	ppm	■ <1	- <1	
Tin	ppm	■ <1	0	
Aluminum	ppm	■<1	■3	
Chromium	ppm	■ <1	1 1	
Molybdenum	ppm	0	< 1	
Nickel	ppm	■<1	0	
Titanium	ppm	0	<1	
Silver	ppm	0	0	
Manganese	ppm	■1	1 1	
Vanadium	ppm	0	0	
VOLVO				
ADDITIV	VES			
Calcium	ppm	■3	□ 28	
Magnesium	ppm	15	4	
Zinc	ppm	□ 7	■24	
Phosphorus	ppm	1042	■257	
Barium	ppm	■0	1 7	

VCES- VOLVO CONSTRUCTION EQUIPMENT

12345 MAPLEVIEW STREET

LAKESIDE, CA US 92040

Contact: Mark Stewart
mark.stewart@vcesvolvo.com

T: X:

F: X:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO4488Unique No:10723077Signed:Wes DavisReport Date:01 Nov 2023



CONSTRUCTION EQUIPMENT





