Sample No: VCP413005

Oil Type: MOBIL WB 102

**Job No:** 489

CAMPI	E INFORMATIO	N		
Sample Number		VCP413005		
Sample Date		18 Oct 2023	 	
Machine Hours		454	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
VOLVO				
OIL CON	IDITION			
Visc @ 40°C	cSt	■80.2	 	
	CSt			
VOLVO				
CONTAI	MINATION			
Silicon	ppm	■35	 	
Sodium	ppm	<b>■</b> 4	 	
Potassium	ppm	<b>2</b>	 	
WEAR	METALS			
Iron	ppm	■83	 	
Copper	ppm	<b>2</b>	 	
Lead	ppm	<b>-&lt;1</b>	 	
Tin	ppm	<b>-&lt;1</b>	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>■1</b>	 	
Molybdenum	ppm	0	 	
Nickel	ppm	<b>-&lt;1</b>	 	
Titanium	ppm	4	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	<1	 	
VOLVO	VEC			
ADDITIV	AC7			
Calcium	ppm	741	 	
Magnesium	ppm	17	 	
Zinc	ppm	1504	 	
Phosphorus	ppm	747	 	
Barium	ppm	0	 	
Boron	ppm	107	 	

Report Id: VOLVO4488 [WUSCAR] 05994720 (Generated: 11/01/2023 15:32:17) Rev: 1

**VCES- VOLVO CONSTRUCTION EQUIPMENT** 

12345 MAPLEVIEW STREET

LAKESIDE, CA US 92040

Contact: Mark Stewart
mark.stewart@vcesvolvo.com

T: X:

F: X:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO4488Unique No:10723080Signed:Wes DavisReport Date:01 Nov 2023



## **CONSTRUCTION EQUIPMENT**





