CONSTRUCTION EQUIPMENT 13735 RYAN VOLVO A45G 353552 - BRAKE COOLING SYSTEM

 Sample No:
 VCP414687

 Oil Type:
 VOLVO WB 102

 Job No:
 13735 RYAN

VOLVO

SAMPLE	INFORMATION			
Sample Number	-	VCP414687	 	
Sample Date		31 Oct 2023	 	
Machine Hours		339	 	
Oil Hours		339	 	
Oil Changed		Not Changd	 	
Sample Status		SEVERE	 	
OIL CON	DITION			
Visc @ 40°C	cSt	41.8	 	
CONTAM	INATION			
Silicon	ppm	27	 	
Sodium	ppm	37	 	
Potassium	ppm	2	 	
WEAR M	ETALS			
Iron	ppm	6 6	 	
Copper	ppm	475	 	
Lead	ppm	5	 	
Tin	ppm	0	 	
Aluminum	ppm	1	 	
Chromium	ppm	1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	4	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	3	 	
Vanadium	ppm	0	 	
ADDITIV	ES		 	
Calcium	nnm	2562		

Calcium	ppm	3563							
Magnesium	ppm	1 3							
Zinc	ppm	1250							
Phosphorus	ppm	1263							
Barium	ppm	0							
Boron	ppm	180							



MCCLUNG-LOGAN EQUIPMENT CO - RICHMOND

1345 MOUNTAIN ROAD GLEN ALLEN, VA US 23060 Contact: KYLE RATLIFFE KRATLIFFE@MCCLUNG-LOGAN.COM T: F: (804)266-1611

Diagnosis

We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.The iron level is abnormal. The copper level is severe. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

 Depot:
 VOLV08882

 Unique No:
 10724780

 Signed:
 Jonathan Hester

 Report Date:
 06 Nov 2023


Contact/Location: KYLE RATLIFFE - VOLVO8882

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Page 2 of 2