

# CONSTRUCTION EQUIPMENT VOLVO A45G 353418 - TRANSMISSION (AUTO)



Sample No: VCP433534

Oil Type: ATF

Job No:

VOLVO	INFORMATIO	V		
	INFURMATIU		 	
Sample Number		VCP433534	 	
Sample Date		20 Oct 2023	 	
Machine Hours		997	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	28.1	 	
VISC @ 40 C	CSL	<b>20.1</b>	 	
VOLVO				
CONTAM	IINATION			
Silicon	ppm	<b>12</b>	 	
Sodium	ppm	<u> </u>	 	
Potassium	ppm	1	 	
	r r	_		
VOLVO	ETALC			
WEAR M	IF I ALZ			
Iron	ppm	<b>25</b>	 	
Copper	ppm	<b>14</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>1</b>	 	
Aluminum	ppm	<b>11</b>	 	
Chromium	ppm	■0	 	
Molybdenum	ppm	<b>0</b>	 	
Nickel	ppm	<b>■</b> <1	 	
Titanium	ppm	0	 	
Silver	ppm	<b>■</b> 0	 	
Manganese	ppm	<b>■</b> 3	 	
Vanadium	ppm	0	 	
VOLVO				
ADDITIV	ES			
Calcium	ppm	<b>7</b> 6	 	
Magnesium	ppm	<b>0</b>	 	
Zinc	ppm	<b>m</b> 5	 	
Phosphorus	ppm	<b>151</b>	 	
Barium	ppm	<b>0</b>	 	
Boron	ppm	<b>86</b>	 	
DOTOTI	ppm			



#### **ALTA EQUIPMENT COMPANY**

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: TODD LARK tlark@altaequipfl.com

T:

F: (239)481-3302

### Diagnosis

The fluid change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. Moderate concentration of visible dirt/debris present in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO0090Unique No:10725363Signed:Don BaldridgeReport Date:04 Nov 2023



## **CONSTRUCTION EQUIPMENT**





