

# CONSTRUCTION EQUIPMENT VOLVO L 150H 7044 - HYDRAULIC SYSTEM



Sample No: VCP376069

Oil Type: VOLVO SUPER HYDRAULIC OIL 46

Job No:

SAMPLE	INFORMATION				
Sample Number		VCP376069			
Sample Date		01 Nov 2023			
Machine Hours		2819			
Oil Hours		0			
Oil Changed		Not Changd			
Sample Status		ABNORMAL			
Sample Status		ADITORIVIAL			
VOLVO					
OIL CON	DITION				
Visc @ 40°C	cSt	<b>42.9</b>			
Acid Number (AN	N) mg KOH/g	<b>0.45</b>			
	, , , , , , , , , , , , , , , , , , , ,				
CONTAI	AINATION				
	MINATION				
Particles >4µm		<u> </u>			
Particles >6µm		<u> </u>			
Particles > 14µm		<b>△</b> 597			
ISO 4406:1999 (c	)	22/20/16			
Silicon	ppm	<b>1</b>			
Sodium	ppm	<b>■1</b>			
Potassium	ppm	<b>■ 0</b>			
WEAR METALS					
		4			
Iron	ppm	<b>1</b>			
Copper	ppm	<b>■</b> 5			
Lead	ppm	<u> </u>			
Tin	ppm	<b>■</b> 0			
Aluminum	ppm	<b>0</b>			
Chromium	ppm	<b>■</b> 0			
Molybdenum	ppm	<b>0</b>			
Nickel	ppm	<b>■</b> 0			
Titanium	ppm	0			
Silver	ppm	0			
Manganese	ppm	<b>0</b>			
Vanadium	ppm	0			
VOLVO					
ADDITIV	ZES				
Calcium	ppm	<b>54</b>			
Magnesium	ppm	O			
Zinc	ppm	<b>■</b> 396			
Phosphorus	ppm	■ 309			
Barium	ppm	<b>0</b>			
Boron	ppm	<b>0</b>			



### **ALTA EQUIPMENT COMPANY**

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: TODD LARK tlark@altaequipfl.com T:

F: (239)481-3302

## Diagnosis

We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a moderate amount of particulates (2 to 100 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

 Depot:
 VOLVO0090

 Unique No:
 10727350

 Signed:
 Wes Davis

 Report Date:
 07 Nov 2023



# **CONSTRUCTION EQUIPMENT**





#### GRAPHS

