

## CONSTRUCTION EQUIPMENT VOLVO A40G 353384 - REAR AXLE



Sample No: VCP432159

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No:

INFORMATION				
INI ORMATION				_
	_			
	ATTENTION			
DITION				
	<b>▲</b> 52 5			
CSt	<u> </u>			
IINATION				
ppm	3			
	<b>3</b>			
	<b>5</b>			
IETAL C				
IF I ALS				
ppm	■279			
ppm	<b>2</b>			
ppm	<b>0</b>			
ppm	<b>0</b>			
ppm	<b>0</b>			
ppm	<b>4</b>			
ppm	<b>4</b>			
ppm	<b>□&lt;1</b>			
ppm	0			
ppm	0			
ppm	<b>12</b>			
ppm	0			
ES				
ppm	<u></u> ▲ 12			
ppm	<b>■</b> 0			
	<u> </u>			
	<b>A</b> 2257			
	<b>0</b>			
- ' '	<b>245</b>			
	DITION  cSt  IIINATION  ppm ppm ppm ppm ppm ppm ppm ppm ppm p	St   S2.5   S2	VCP432159  02 Nov 2023  1237  Changed  ATTENTION  CSt	VCP432159



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

## Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type.

Depot:VOLVO0093Unique No:10727757Signed:Don BaldridgeReport Date:08 Nov 2023



## **CONSTRUCTION EQUIPMENT**





## GRAPHS

