

## CONSTRUCTION EQUIPMENT VOLVO A40G 353384 - FRONT AXLE



Sample No: VCP432152

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No:

SAMPLE	INFORMATION	N		
Sample Number		VCP432152	 	
Sample Date		02 Nov 2023	 	
Machine Hours		1237	 	
Oil Hours		1237	 	
Oil Changed		Changed	 	
Sample Status		ATTENTION	 	
VOLVO	DITION			
OIL CON			 <u>.</u>	
Visc @ 40°C	cSt	<b>△</b> 51.6	 	
VOLVO				
CONTAN	MINATION			
Silicon	ppm	<b>6</b>	 	
Sodium		■3	 	
Potassium	ppm	■3	 	
rotassium	ррпп	3	 	
VOLVO				
WEAR N	METALS			
Iron	ppm	■325	 	
Copper	ppm	■1	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>■</b> 0	 	
Aluminum	ppm	<b>0</b>	 	
Chromium	ppm	<b>4</b>	 	
Molybdenum	ppm	■3	 	
Nickel	ppm	<b>■&lt;1</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>14</b>	 	
Vanadium	ppm	0	 	
VOLVO				
ADDITIV	/ES			
Calcium	ppm	<u></u> 12	 	
Magnesium	ppm	<b>■</b> 0	 	
Zinc	ppm	<b>14</b>	 	
Phosphorus	ppm	<b>2266</b>	 	
Barium	ppm	<b>0</b>	 	
Boron	ppm	<b>200</b>	 	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

## Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type.

Depot:VOLVO0093Unique No:10727760Signed:Don BaldridgeReport Date:08 Nov 2023



## **CONSTRUCTION EQUIPMENT**





