

CONSTRUCTION EQUIPMENT TITAN VOLVO EC380E 315183 - SWING DRIVE



Sample No: VCP413697

Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5

Job No: TITAN

VOLVO	INCORMATION			
	INFORMATION			
Sample Number		VCP413697	VCP401972	
Sample Date		07 Nov 2023	27 Apr 2023	
Machine Hours		2000	1125	
Oil Hours		0	1000	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	ABNORMAL	
OIL CON	DITION			
Visc @ 40°C	cSt	121	□176	
VOLVO				
CONTAM	IINATION			
Water	%	NEG	NEG	
Silicon	ppm	63	2 4	
Sodium	ppm	1	2	
Potassium	ppm	4	1	
VOLVO	IFTAL C			
WEAR M	IF I ALS			
Iron	ppm	■170	<u> </u>	
Copper	ppm	■0	▲ 72	
Lead	ppm	■ 0	0	
Tin	ppm	■0	- <1	
Aluminum	ppm	11	7	
Chromium	ppm	■8	1 8	
Molybdenum	ppm		2	
Nickel	ppm	■0	- <1	
Titanium	ppm	<1	<1	
Silver	ppm	0	0	
Manganese	ppm	2	1 6	
Vanadium	ppm	0	0	
ADDITIV	ES			
Calcium	ppm	12	□28	
Magnesium	ppm	1	3	
Zinc	ppm	11	□ 52	
Phosphorus	ppm	747	■341	
Barium	ppm	0	0	
Boron	ppm	77	□0	



MCCLUNG-LOGAN EQUIPMENT CO - CHESAPEAKE
4112 HOLLAND BLVD
CHESAPEAKE, VA
US 23323
Contact: TOMMY GRIFFIN
tgriffin@mcclung-logan.com
T: (757)485-3314
F: (757)485-3415

Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0264Unique No:10740957Signed:Doug BogartReport Date:04 Dec 2023



CONSTRUCTION EQUIPMENT





