



CONSTRUCTION EQUIPMENT

367 HITACHI 9405 10 - SWING DRIVE



Sample No: VCP426351
Oil Type: DRYDENE 80W90
Job No: 367



SAMPLE INFORMATION

Sample Number	VCP426351	---	---	---
Sample Date	07 Oct 2023	---	---	---
Machine Hours	6420	---	---	---
Oil Hours	1000	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

TOTAL DEVELOPMENT SOLUTIONS LLC
 7805 PROGRESS CT
 GAINESVILLE, VA
 US 20155
 Contact: JOE SEALE
 jseale@totaldevelopmentsolutions.com
 T: (703)222-0497
 F: (703)753-4586



OIL CONDITION

Visc @ 40°C	cSt	█ 141	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 5	---	---	---
Sodium	ppm	█ <1	---	---	---
Potassium	ppm	█ 0	---	---	---



WEAR METALS

Iron	ppm	█ 55	---	---	---
Copper	ppm	█ <1	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	<1	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	8	---	---	---
Magnesium	ppm	2	---	---	---
Zinc	ppm	0	---	---	---
Phosphorus	ppm	812	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	131	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: TOTGAI
Unique No: 10750870
Signed: Angela Borella
Report Date: 21 Nov 2023



CONSTRUCTION EQUIPMENT



GRAPHS

