

CONSTRUCTION EQUIPMENT 9941 VOLVO L70G 614340 - FRONT AXLE



Sample No: VCP388527
Oil Type: VOLVO WB 102

Job No: 9941

SAMPLE	INFORMATION				
Sample Number		VCP388527	VCP290943	VCP220451	VCP196121
Sample Date		20 Nov 2023	06 Nov 2020	30 Oct 2018	07 Jun 2016
Machine Hours		12078	9117	5998	2300
Oil Hours		0	0	0	0
Oil Changed		Changed	Changed	Changed	Changed
Sample Status		ABNORMAL	NORMAL	NORMAL	ABNORMAL
OIL CON	DITION				
Visc @ 40°C	cSt	41.1	40.6	45.34	47.34
CONTAM	MINATION				
Water	%	NEG	NEG	NEG	△ 0.558
Silicon	ppm	■ 9	9	■9	■18
Sodium	ppm	6	1		■11
Potassium	ppm	■0	0	4	 <1
WEAR M					
Iron	ppm	19	2 4	1 9	4 3
Copper	ppm	2	= <1	- <1	8
Lead	ppm		- <1	0	0
Tin	ppm	<u>^</u> 21	= <1	0	- <1
Aluminum	ppm	1 <1	- <1	= <1	□ < 1 □
Chromium	ppm	■<1	<1	= <1	1
Molybdenum	ppm	6	- <1	1	0
Nickel	ppm	0	0	0	3
Titanium	ppm	0	<1	<1	0
Silver	ppm	0	0	0	0
Manganese	ppm		- <1	- <1	2
Vanadium	ppm	<1	0	<1	0
VOLVO					
ADDITIV	<u> </u>				
Calcium	ppm	■3166	■3323	■3624	■3597
Magnesium	ppm	47	1 1	■8	1 0
Zinc	ppm	■1358	□1339	■ 1478	■1378
Phosphorus	ppm	1155	1090	□1128	1206
Barium	ppm	0	0	0	- <1
Boron	ppm	109	114	106	■118



RELIABLE CONTRACTING

2410 EVERGREEN RD SUITE 200
GAMBRILLS, MD
US 21054
Contact: RUSSELL HATFIELD
RHATFIELD@RELIABLECONTRACTING.COM
T: (410)987-1851
F:

Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. The tin level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot:RELMILUnique No:10762992Signed:Don BaldridgeReport Date:30 Nov 2023



CONSTRUCTION EQUIPMENT





