

CONSTRUCTION EQUIPMENT RA87 VOLVO L70H 624378 - FRONT AXLE



Sample No: VCP374209
Oil Type: VOLVO WB 102

Job No: RA87

VOLVO CAMPI	E INFORMATIO	N		
		<u> </u>		
Sample Number		VCP374209	 	
Sample Date		20 Nov 2023	 	
Machine Hours		984	 	
Oil Hours		1000	 	
Oil Changed		Not Changd	 	
Sample Status		MARGINAL	 	
OIL CON	IDITION			
Visc @ 40°C	cSt	41.5	 	
	CSt	— 41.3		
VOLVO				
CONTAI	MINATION			
Water	%	△ 0.233	 	
Silicon	ppm	12	 	
Sodium	ppm	13	 	
Potassium	ppm	O	 	
VOLVO	AETAL C			
WEAR	METAL2			
Iron	ppm	68	 	
Copper	ppm	■27	 	
Lead	ppm	■<1	 	
Tin	ppm	2	 	
Aluminum	ppm	■<1	 	
Chromium	ppm	■3	 	
Molybdenum	ppm	3	 	
Nickel	ppm	■ 0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	10	 	
Vanadium	ppm	<1	 	
ADDITI	VFS			
_		= 2700		
Calcium	ppm	■3789	 	
Magnesium	ppm	11	 	
Zinc	ppm	■ 1514	 	
Phosphorus	ppm	■ 1322	 	
Barium	ppm	0	 	
Boron	ppm	125	 	



HOUSBY HEAVY EQUIPMENT, LLC

4410 SE 4 MILE DR ANKENY, IA US 50021 Contact: RANDY VANDERLEEST rvanderleest@housby.com T: F: (515)964-2865

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is a light concentration of water present in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0080Unique No:10762999Signed:Don BaldridgeReport Date:30 Nov 2023



CONSTRUCTION EQUIPMENT





GRAPHS

