



# CONSTRUCTION EQUIPMENT

SPM633258 CADILLAC A VOLVO L25H 1420331 - REAR AXLE



**Sample No:** VCP409120  
**Oil Type:** GEAR OIL SAE 80W90  
**Job No:** SPM633258 CADILLAC A



**ALTA CONSTRUCTION EQUIPMENT LLC**  
 G-3283 S. DORT HIGHWAY  
 BURTON, MI  
 US 48529  
 Contact: BURTON SERVICE  
 BURTON.SERVICE@ALTAEQUIPMENT.COM  
 T:  
 F:



## SAMPLE INFORMATION

Sample Number	VCP409120	---	---	---
Sample Date	17 Nov 2023	---	---	---
Machine Hours	1509	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	ATTENTION	---	---	---



## OIL CONDITION

Visc @ 40°C	cSt	▲ 63.3	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 12	---	---	---
Sodium	ppm	■ 20	---	---	---
Potassium	ppm	■ 2	---	---	---



## WEAR METALS

Iron	ppm	■ 215	---	---	---
Copper	ppm	■ 4	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ <1	---	---	---
Aluminum	ppm	■ 1	---	---	---
Chromium	ppm	■ 4	---	---	---
Molybdenum	ppm	■ <1	---	---	---
Nickel	ppm	■ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 11	---	---	---
Vanadium	ppm	<1	---	---	---



## ADDITIVES

Calcium	ppm	■ 3245	---	---	---
Magnesium	ppm	■ 11	---	---	---
Zinc	ppm	■ 1327	---	---	---
Phosphorus	ppm	■ 1126	---	---	---
Barium	ppm	■ 1	---	---	---
Boron	ppm	■ 118	---	---	---

## Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type.

**Depot:** VOLVO5023  
**Unique No:** 10765245  
**Signed:** Don Baldrige  
**Report Date:** 03 Dec 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

