Sample No: VCP440798

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

**Job No:** 621908 PRECISION PAV

VOLVO SAMPLE	E INFORMATIO	IN .		
Sample Number		VCP440798	 	
Sample Number		03 Nov 2023	 	
Machine Hours		2113	 	
Oil Hours		1000	 	
Oil Changed		Changed	 	
Sample Status		SEVERE	 	
		JEVERE	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>278</b>	 	
VOLVO	MINATION			
_	MINATION			
Water	%	NEG	 	
Silicon	ppm	<b>297</b>	 	
Sodium	ppm	■2	 	
Potassium	ppm	<b>1</b>	 	
VOLVO				
WEAR N	AFTAI S			
Iron		<b>1823</b>	 	
	ppm	■ 1023	 	
Copper Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>■</b> <1	 	
Aluminum	ppm	<u> </u>	 	
Chromium	ppm	▲ 22	 	
Molybdenum	ppm	<u> </u>	 	
Nickel	ppm	<b>4</b>	 	
Titanium	ppm	1	 	
Silver	ppm	0	 	
	ppm	<b>□</b> 12	 	
Manganese Vanadium	ppm	<1	 	
vallaululii	ppm	<1	 	
VOLVO				
ADDITIV	VES			
Calcium	ppm	<b>513</b>	 	
Magnesium	ppm	<b>1</b> 4	 	
Zinc	ppm	<b>■ 172</b>	 	
Phosphorus	ppm	<b>899</b>	 	
Barium	ppm	<b>4</b>	 	
Boron	ppm	<b>125</b>	 	
		_		

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077

## Diagnosis

F: (813)630-2233

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. Gear wear is indicated. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. The oil is no longer serviceable due to the presence of contaminants.

Depot:VOLVO0093Unique No:10765273Signed:Don BaldridgeReport Date:03 Dec 2023



## **CONSTRUCTION EQUIPMENT**





