

CONSTRUCTION EQUIPMENT SWA413863 RENTAL VOLVO A45GFS 352236 - BRAKE COOLING

Sample No: VCP440634 Oil Type: VOLVO WB 102

Job No: SWA413863 RENTAL

| VOLVO SAMPLE | INFORMATION | ı | | |
|---------------|-------------|----------------|------|--|
| | | | | |
| Sample Number | | VCP440634 | | |
| Sample Date | | 21 Nov 2023 | | |
| Machine Hours | | 7297 | | |
| Oil Hours | | 0 | | |
| Oil Changed | | Not Changd | | |
| Sample Status | | ABNORMAL | | |
| VOLVO | | | | |
| OIL CON | DITION | | | |
| Visc @ 40°C | cSt | 41.1 | | |
| VISC @ 40 C | CSt | | | |
| VOLVO | | | | |
| CONTAM | IINATION | | | |
| Water | % | NEG | | |
| Silicon | ppm | 15 | | |
| Sodium | ppm | ■ 9 | | |
| Potassium | ppm | -< 1 | | |
| | | | | |
| VOLVO | IETAL C | | | |
| WEAR M | IF I ALS | | | |
| Iron | ppm | 6 | | |
| Copper | ppm | <u> </u> | | |
| Lead | ppm | 4 | | |
| Tin | ppm | ■<1 | | |
| Aluminum | ppm | ■<1 | | |
| Chromium | ppm | ■<1 | | |
| Molybdenum | ppm | ■<1 | | |
| Nickel | ppm | ■ 5 | | |
| Titanium | ppm | 0 | | |
| Silver | ppm | 0 | | |
| Manganese | ppm | 1 | | |
| Vanadium | ppm | <1 | | |
| | | | | |
| ADDITIV | /FC | | | |
| _ | - | =2474 | | |
| Calcium | ppm | ■3174 | | |
| Magnesium | ppm | 8 | | |
| Zinc | ppm | ■ 1391 | | |
| Phosphorus | ppm | 1210 | | |
| Barium | ppm | 0 | | |
| Boron | ppm | 107 | | |



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: KENNY HANEY khaney@flaglerce.com T: (813)630-0077 F: (813)630-2233

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: VOLVO0093 **Unique No:** 10765296 Signed: Don Baldridge Report Date: 03 Dec 2023



CONSTRUCTION EQUIPMENT





GRAPHS

