

# CONSTRUCTION EQUIPMENT RA88 VOLVO EC200E 314983 - SWING DRIVE



Sample No: VCP374200

Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5

Job No: RA88

ZAMPI F	INFORMATION				
	INI ONIMATION				
Sample Number		VCP374200			
Sample Date		28 Nov 2023			
Machine Hours		534			
Oil Hours		500			
Oil Changed		Changed			
Sample Status		NORMAL			
VOLVO					
OIL CONDITION					
Visc @ 40°C	cSt	<b>181</b>			
VOLVO					
COLVO	INATION				
Water	%	NEG			
Silicon	ppm	<b>16</b>			
Sodium	ppm	■0			
Potassium	ppm	<b></b>			
WEAR M	ETALS				
Iron	ppm	<b>9</b> 3			
Copper	ppm	<b>1</b> 74			
Lead		■0			
Tin	ppm	■0			
Aluminum	ppm	<b>■</b> 2			
Chromium	ppm	■2 ■1			
Molybdenum	ppm	■ <1			
Nickel	ppm	■<1 ■<1			
Titanium	ppm	0			
Silver	ppm	0			
Manganese	ppm	■4			
_	ppm	0			
Vanadium	ppm	U			
VOLVO					
<b>ADDITIV</b>	ES				
Calcium	ppm	<b>1</b> 9			
Magnesium	ppm	<u> </u>			
Zinc	ppm	<u></u> 44			
Phosphorus	ppm	<b>319</b>			
Barium	ppm	<b>6</b>			
Boron	ppm	■0			
	PP				



### **HOUSBY HEAVY EQUIPMENT, LLC** 4410 SE 4 MILE DR

ANKENY, IA
US 50021
Contact: RANDY VANDERLEEST
rvanderleest@housby.com
T:

F: (515)964-2865

### Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. Metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0080Unique No:10768672Signed:Don BaldridgeReport Date:06 Dec 2023



## **CONSTRUCTION EQUIPMENT**





