Sample No: VCP404808

Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5

**Job No:** X13689

VOLVO CAMPIE	INFORMATIO	N		
	. IIVI OMPIATIOI		<u></u>	
Sample Number		VCP404808		 
Sample Date		28 Nov 2023		 
Machine Hours		468		 
Oil Hours		468		 
Oil Changed		Changed		 
Sample Status		ABNORMAL		 
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>143</b>		 
VOLVO				
CONTAN	MINATION			
Water	%	■ 0.087		 
Silicon	ppm	<b>14</b>		 
Sodium	ppm	<b>5</b>		 
Potassium	ppm	<b>2</b>		 
VOLVO	AFTAL C			
WEAR N	JE I ALS			
Iron	ppm	<u> </u>		 
Copper	ppm	■5		 
Lead	ppm	■0		 
Tin	ppm	<b>■</b> 0		 
Aluminum	ppm	■8		 
Chromium	ppm	<b>■</b> 9		 
Molybdenum	ppm	<b>■&lt;1</b>		 
Nickel	ppm	<b>1</b>		 
Titanium	ppm	3		 
Silver	ppm	0		 
Manganese	ppm	<b>23</b>		 
Vanadium	ppm	0		 
ADDITIV	/ES			
Calcium	_	<b>1</b> 5		 
Magnesium	ppm	<b>2</b>		 
Zinc	ppm	■2 ■86		 
Phosphorus	ppm	■ 783		 
Barium	ppm	■ 783 ■ 44		 
	ppm			
Boron	ppm	■82		 

SCOTT EQUIPMENT COMPANY LLC - Broussard 100 IDA ROAD BROUSSARD, LA

US 70518 Contact: ALISON HARGRODER ahargroder@scottcompanies.com

T: (337)837-2907 F: (337)837-5116

## Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. Gear wear is indicated. All other metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO6241Unique No:10768675Signed:Don BaldridgeReport Date:06 Dec 2023



## **CONSTRUCTION EQUIPMENT**





