

# CONSTRUCTION EQUIPMENT VOLVO ECR145 315439 - DIESEL ENGINE



Sample No: VCP441857

Oil Type: DIESEL ENGINE OIL SAE 40

Job No:

VOLVO				
SAMPLE II	NFORMATION			
Sample Number	-	VCP441857	 	
Sample Date		13 Oct 2023	 	
Machine Hours		1481	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CONDI	TION			
Visc @ 100°C	cSt	<b>12.7</b>	 	
		■ 12.7 ■ 10.4		
Base Number (BN) Oxidation (PA)	mg KOH/g %	81	 	
Oxidation (PA)	70	01	 	
VOLVO				
CONTAMIN	NATION			
Water	%	NEG	 	
Soot %	%	■ 0.2	 	
Nitration (PA)	%	60	 	
Sulfation (PA)	%	59	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	<b>■8</b>	 	
Sodium	ppm	<b>■</b> <1	 	
Potassium	ppm	<b>1</b>	 	
WEAR ME	TALS			
Iron	ppm	<b>13</b>	 	
Copper	ppm	<b>2</b>	 	
Lead	ppm	■0	 	
Tin	ppm	0	 	
Aluminum	ppm	<b>4</b>	 	
Chromium	ppm	<b>□&lt;1</b>	 	
Molybdenum	ppm	<b>42</b>	 	
Nickel	ppm	■0	 	
Titanium	ppm	■0	 	
Silver	ppm	■0	 	
Manganese	ppm	■0	 	
Vanadium	ppm	0	 	
ADDITIVE:				
Calcium	ppm	<b>1644</b>	 	
Magnesium	ppm	<b>472</b>	 	
Zinc	ppm	<b>1058</b>	 	
Phosphorus	ppm	■869	 	
Barium	ppm	<b>2</b>	 	
Boron	ppm	■36	 	



#### **RIPA AND ASSOCIATES**

10149 FISHER AVENUE TAMPA, FL US 33619 Contact: PM Services PMServices@ripaconstruction.com T: F:

### Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DIESEL ENGINE OIL SAE 40. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:RIPTAMUnique No:10776003Signed:Wes DavisReport Date:07 Dec 2023



## **CONSTRUCTION EQUIPMENT**





