

## **CONSTRUCTION EQUIPMENT**

HERC RENTALS VOLVO ECR 145EL 315866 - REAR RIGHT FINAL DR

Sample No: VCP436030

Oil Type: NOT GIVEN

Job No: HERC RENTALS

SAMPLE	INFORMATIO	V		
Sample Number	<u>.</u>	VCP436030	 	
Sample Date		09 Oct 2023	 	
Machine Hours		598	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
		, , , , , , , , , , , , , , , , , , , ,		
VOLVO	DITION			
OIL CON	NITIUN			
Visc @ 40°C	cSt	138	 	
CONTAN	MINATION			
Water	%	NEG	 	
Silicon Sodium	ppm	<b>10</b>	 	
	ppm	<b>6</b>	 	
Potassium	ppm	■0	 	
VOLVO				
WEAR M	<b>METALS</b>			
Iron	ppm	<b>199</b>	 	
Copper	ppm	<b>-&lt;1</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>17</b>	 	
Aluminum	ppm	<b>■</b> 0	 	
Chromium	ppm	<b>4</b>	 	
Molybdenum	ppm	0	 	
Nickel	ppm	<b>■</b> 0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	4	 	
Vanadium	ppm	0	 	
ADDITIV	/ES			
Calcium	ppm	19	 	
Magnesium	ppm	0	 	
Zinc	ppm	21	 	
Phosphorus	ppm	195	 	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

## Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0093Unique No:10776640Signed:Jonathan HesterReport Date:08 Dec 2023

0

ppm

ppm

Barium

Boron



## **CONSTRUCTION EQUIPMENT**





