

CONSTRUCTION EQUIPMENT VOLVO EC480E 314844 - LEFT SWING DRIVE



Sample No: VCP398427

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No:

ZAMPI F	INFORMATIO	N		
Sample Number	. IIII OMPIMITO	VCP398427	VCP390758	
		04 Dec 2023	14 Oct 2022	
Sample Date Machine Hours		2613	528	
Oil Hours		0	0	
Oil Changed		Changed	Changed	
Sample Status		ABNORMAL	NORMAL	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	178	167	
		_		
VOLVO	AIN A TION			
LUNIAN	MINATION			
Water	%	△ 0.397	NEG	
Silicon	ppm	■ 51	■26	
Sodium	ppm	0	0	
Potassium	ppm	2	0	
WEAR N	AFTALS			
		A 4040		
Iron	ppm	<u>▲</u> 1218	■356	
Copper	ppm	■34	10	
Lead	ppm	■ <1	0	
Tin	ppm	0	<1	
Aluminum	ppm	3	2	
Chromium	ppm	<u> </u>	5	
Molybdenum	ppm	2	- <1	
Nickel	ppm	1	0	
Titanium	ppm	<1	<1	
Silver	ppm	0	0	
Manganese	ppm	13	5	
Vanadium	ppm	0	0	
VOLVO				
ADDITIV	/ES			
Calcium	-	22	1 2	
	ppm	3	<1	
Magnesium Zinc	ppm	■ 61	<u></u> 11	
Phosphorus	ppm	429	327	
Barium	ppm	□ 429	_	
	ppm		4	
Boron	ppm	□0	0	



ALTA EQUIPMENT COMPANY
5151 DR MARTIN LUTHER KING BLVD
FORT MYERS, FL
US 33905
Contact: TODD LARK
tlark@altaequipfl.com
T:

F: (239)481-3302

Diagnosis

We advise that you check for the source of water entry. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. Gear wear is indicated. There is a moderate concentration of water present in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0090Unique No:10777034Signed:Jonathan HesterReport Date:12 Dec 2023



CONSTRUCTION EQUIPMENT





