### CONSTRUCTION EQUIPMENT 621739 VOLVO EC750 310137 - COOLANT



Sample No:VCP434764Oil Type:VOLVO COOLANT VCS (YELLOW)

VOLVO

**Job No:** 62

621739

SAMPLE II	NFORMATION			
Sample Number	-	VCP434764	 	
Sample Date		30 Nov 2023	 	
Machine Hours		6059	 	
Sample Status		NORMAL	 	
COOL ANT	CONDITION			
pH	Scale 0-14	7.10	 	
Reserve Alkalinity	Scale 0-20		 	
Nitrites	ppm	<b>■</b> NT	 	
Percentage Glycol	%	52.8	 	
Freezing Point	°C	<b>-40</b>	 	
CONTAMI				
		<u> </u>		
Coolant Appearance		normal	 	
Coolant Color		Yllow	 	



**BLAZE CONSTRUCTION** 

5640 ST JEAN ST DETROIT, MI US 48213 Contact: DAVE WARD dward@blazecontracting.net T: (248)632-2317 F:

#### Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:BLADETUnique No:10779627Signed:Jonathan HesterReport Date:13 Dec 2023


# **CONSTRUCTION EQUIPMENT**



## GRAPHS

#### Iron/Tin/Silver

VOLVO



Report Id: BLADET [WUSCAR] 06029836 (Generated: 12/13/2023 14:15:51) Rev: 1

Contact/Location: DAVE WARD - BLADET