

## CONSTRUCTION EQUIPMENT 634759 RUBYS VOLVO EC220 314072 - SWING DRIVE



Sample No: VCP435393

Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5

**Job No:** 634759 RUBYS

VOLVO	INFORMATIO	NI		
	INFORMATIO	N	 	
Sample Number		VCP435393	 	
Sample Date		06 Dec 2023	 	
Machine Hours		3106	 	
Oil Hours		1106	 	
Oil Changed		Changed	 	
Sample Status		ATTENTION	 	
OIL COND	DITION			
Visc @ 40°C	cSt	<b>333</b>	 	
VOLVO	INATION			
CONTAM				
Water	%	NEG	 	
Silicon	ppm	<b>18</b>	 	
Sodium	ppm	■0	 	
Potassium	ppm	■1	 	
VOLVO				
WEAR M	ETALS			
Iron	ppm	<b>455</b>	 	
Copper	ppm	<b>16</b>	 	
Lead	ppm	<b>-&lt;1</b>	 	
Tin	ppm	■0	 	
Aluminum	ppm	<b>3</b>	 	
Chromium	ppm	<b>2</b>	 	
Molybdenum	ppm	<b>-&lt;1</b>	 	
Nickel	ppm	<b>■&lt;1</b>	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	<b>4</b>	 	
Vanadium	ppm	0	 	
ADDITIV	ES			
Calcium	ppm	<b>5</b> 4	 	
Magnesium	ppm	<u> </u>	 	
Zinc	ppm	■25	 	
Phosphorus	ppm	<b>1106</b>	 	
Barium	ppm	■8	 	
Boron	ppm	<b>194</b>	 	



ALTA EQUIPMENT COMPANY - METRO WEST 56195 PONTIAC TRAIL NEW HUDSON, MI US 48165 Contact: PAUL CONZ paul.conz@altg.com T: (313)348-8861 F: (248)356-2029

## Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is higher than normal. Confirm oil type.

Depot:VOLVO2990Unique No:10794914Signed:Jonathan HesterReport Date:21 Dec 2023



## **CONSTRUCTION EQUIPMENT**





