

## CONSTRUCTION EQUIPMENT VOLVO A40G 352489 - WET DISC BRAKE



Sample No: VCP436206
Oil Type: VOLVO WB 102

Job No:

CAMPLE	INFORMATION	<u> </u>		
	. IIII UMPIATIOI		VCD244047	
Sample Number		VCP436206	VCP344047	 
Sample Date		13 Dec 2023	04 Nov 2021	 
Machine Hours		6270	2129	 
Oil Hours		0	0	 
Oil Changed		Changed	Not Changd	 
Sample Status		ABNORMAL	ABNORMAL	 
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	□39.4	□39.5	 
VISC @ 40 C	CSt		33.3	
VOLVO				
CONTAN	MINATION			
Water	%	NEG	NEG	 
Silicon	ppm	<b>19</b>	<b>1</b> 9	 
Sodium	ppm	<b>■8</b>	<b>1</b> 2	 
Potassium	ppm	<b>0</b>	<b>0</b>	 
WEAR N	AETAL C			
WEAK	JE I HEZ			
Iron	ppm	<b>17</b>	□15	 
Copper	ppm	<u> </u>	<u>^</u> 244	 
Lead	ppm	<b>4</b>	<b>-</b> <1	 
Tin	ppm	<b>■</b> 0	<b>-</b> <1	 
Aluminum	ppm	<b>■&lt;1</b>	<b>&lt;</b> 1	 
Chromium	ppm	<b>■&lt;1</b>	<b>-</b> <1	 
Molybdenum	ppm	<b>■&lt;1</b>	<b></b>	 
Nickel	ppm	<b>7</b>	6	 
Titanium	ppm	0	0	 
Silver	ppm	0	<1	 
Manganese	ppm	<b>1</b>	<b>1</b>	 
Vanadium	ppm	<1	0	 
ADDITIV	/FS			
_		2050	m 2070	 
Calcium	ppm	3050	3970	
Magnesium	ppm	<b>■</b> 0	□10 □1560	 
Zinc	ppm	<b>1296</b>	□1568	 
Phosphorus	ppm	<b>1127</b>	1388	 
Barium	ppm	<b>0</b>	0	 
Boron	ppm	<b>106</b>	<b>141</b>	 



## **ALTA EQUIPMENT COMPANY**

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: TODD LARK tlark@altaequipfl.com T:

F: (239)481-3302

## Diagnosis

No corrective action is recommended at this time. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0090Unique No:10796042Signed:Jonathan HesterReport Date:22 Dec 2023



## **CONSTRUCTION EQUIPMENT**





