

Sample No: VCP413423 Oil Type: VOLVO

**Job No:** X10976 OLDCASTLE

VOLVO CAMPI	E INFORMATIO	N		
			<u> </u>	<u> </u>
Sample Number		VCP413423		 
Sample Date		15 Dec 2023		 
Machine Hours		713		 
Oil Hours		713		 
Oil Changed		Not Changd		 
Sample Status		ABNORMAL		 
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	28.3		 
VOLVO				 
CONTAN	MOITANIN			
Water	%	NEG		 
Silicon	ppm	<b>10</b>		 
Sodium	ppm	<b>2</b>		 
Potassium	ppm	<b>■&lt;1</b>		 
VOLVO	ACTAL C			
WEAR N	METAL2			
Iron	ppm	■98		 
Copper	ppm	<b>5</b>		 
Lead	ppm	<b>■&lt;1</b>		 
Tin	ppm	■0		 
Aluminum	ppm	<b>■&lt;1</b>		 
Chromium	ppm	<b>■&lt;1</b>		 
Molybdenum	ppm	0		 
Nickel	ppm	■0		 
Titanium	ppm	0		 
Silver	ppm	<b>■</b> 0		 
Manganese	ppm	6		 
Vanadium	ppm	<1		 
ADDITIV	VFS			
_		60		
Calcium	ppm	60		 
Magnesium	ppm	0		 
Zinc	ppm	8		 
Phosphorus	ppm	140		 
Barium	ppm	0		 
Boron	ppm	76		 



SCOTT EQUIPMENT COMPANY LLC - Texarkana 5401 SANDERSON LANE TEXARKANA, AR US 71854 Contact: D. BELL dbell@scottcompanies.com T: (870)772-0204 F:

## Diagnosis

We recommend you service the filters on this component. Resample at the next service interval to monitor. Moderate concentration of visible metal present. All component wear rates are normal. Moderate concentration of visible dirt/debris present in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO1034Unique No:10796097Signed:Don BaldridgeReport Date:22 Dec 2023



## **CONSTRUCTION EQUIPMENT**





