

Sample No: VCP449108
Oil Type: VOLVO

Job No: X10975 OLDCASTLE

VOLVO CAMPI	E INFORMATIO	N		
	L IINI ONMATIO		 	
Sample Number		VCP449108	 	
Sample Date		15 Dec 2023	 	
Machine Hours		737	 	
Oil Hours		737	 	
Oil Changed		Not Changd	 	
Sample Status		ABNORMAL	 	
OIL CON	IDITION			
Visc @ 40°C	cSt	□ 28.8	 	
	CSt			
VOLVO				
CONTAN	MINATION			
Water	%	NEG	 	
Silicon	ppm	■ 9	 	
Sodium	ppm	■2	 	
Potassium	ppm	 <1	 	
Otassiani	PPIII			
VOLVO				
WEAR N	METALS			
Iron	ppm	148	 	
Copper	ppm	■ 5	 	
Lead	ppm	-<1	 	
Tin	ppm	0	 	
Aluminum	ppm	■ <1	 	
Chromium	ppm	■ <1	 	
Molybdenum	ppm	<1	 	
Nickel	ppm	■0	 	
Titanium	ppm	0	 	
Silver	ppm	■0	 	
Manganese	ppm	7	 	
Vanadium		, <1	 	
vallaululli	ppm	~ 1		
VOLVO			 	
ADDITIV	VES			
Calcium	ppm	58	 	
Magnesium	ppm	0	 	
Zinc	ppm	10	 	
Phosphorus	ppm	141	 	
Barium	ppm	0	 	
Boron		74	 	
DOTOIT	ppm	14		



SCOTT EQUIPMENT COMPANY LLC - Texarkana 5401 SANDERSON LANE TEXARKANA, AR US 71854 Contact: D. BELL dbell@scottcompanies.com T: (870)772-0204 F:

Diagnosis

We recommend you service the filters on this component. Resample at the next service interval to monitor. Moderate concentration of visible metal present. All component wear rates are normal. No other contaminants were detected in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO1034Unique No:10796098Signed:Don BaldridgeReport Date:22 Dec 2023



CONSTRUCTION EQUIPMENT





