### CONSTRUCTION EQUIPMENT SW0-068393 VOLVO EC480EL 315428 - COOLANT



 Sample No:
 VCP447582

 Oil Type:
 VOLVO COOLANT VCS (YELLOW)

 Job No:
 SWO-068393

VOLVO

| SAMPLE I           | FORMATION  |             |  |  |  |
|--------------------|------------|-------------|--|--|--|
| Sample Number      | -          | VCP447582   |  |  |  |
| Sample Date        |            | 19 Dec 2023 |  |  |  |
| Machine Hours      |            | 482         |  |  |  |
| Sample Status      |            | NORMAL      |  |  |  |
|                    |            |             |  |  |  |
| COOLANT CONDITION  |            |             |  |  |  |
| рН                 | Scale 0-14 | 8.11        |  |  |  |
| Reserve Alkalinity | Scale 0-20 |             |  |  |  |
| Nitrites           | ppm        | NT NT       |  |  |  |
| Percentage Glycol  | %          | 51.3        |  |  |  |
| Freezing Point     | °C         | 38          |  |  |  |
|                    |            |             |  |  |  |
| CONTAMINATION      |            |             |  |  |  |
| Coolant Appearance |            | normal      |  |  |  |
| Coolant Color      |            | Yllow       |  |  |  |



SAIIA CONSTRUCTION LLC

4400 LEWISBURG RD BIRMINGHAM, AL US 35207 Contact: STEPHANI BRITTON sbritton@saiia.com;doug.bogart@wearcheck.com T: (205)943-2268 F: (205)943-2269

#### Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

 Depot:
 SAIBIR

 Unique No:
 10804333

 Signed:
 Jonathan Hester

 Report Date:
 29 Dec 2023


## **CONSTRUCTION EQUIPMENT**



# GRAPHS

#### Iron/Tin/Silver

VOLVO



Report Id: SAIBIR [WUSCAR] 06043725 (Generated: 12/29/2023 10:41:04) Rev: 1

Contact/Location: STEPHANI BRITTON - SAIBIR