

CONSTRUCTION EQUIPMENT
SW1027835 STEFFY VOLVO ECR235E 314278 - REAR RIGHT FINA

Sample No: VCP415114

Oil Type: **GEAR OIL SAE 80W90** Job No: SW1027835 STEFFY

VOLVO	INFORMATION			
	INFURMATIUN			
Sample Number		VCP415114	VCP406937	 
Sample Date		16 Dec 2023	15 Jul 2023	 
Machine Hours		2210	1700	 
Oil Hours		0	0	 
Oil Changed		Changed	Changed	 
Sample Status		ABNORMAL	ABNORMAL	 
OIL CON	NITION			
		= 4.45	- 17.4	
Visc @ 40°C	cSt	<b>145</b>	<b>□</b> 174	 
VOLVO				
CONTAM	IINATION			
Water	%	NEG	NEG	 
Silicon	ppm	■21	25	 
Sodium	ppm	■0	<u>5</u>	 
Potassium	ppm	<b>1</b> 4	3	 
T Stassiani	ррт			
VOLVO				
WEAR M	IETALS			
Iron	ppm	<u></u> 570	<b>△</b> 518	 
Copper	ppm	<b>■&lt;1</b>	<b>-</b> <1	 
Lead	ppm	<b>0</b>	<b>0</b>	 
Tin	ppm	<b>■</b> 0	<b>0</b>	 
Aluminum	ppm	<b>2</b>	<b>6</b>	 
Chromium	ppm	<b>■</b> 7	<u> </u>	 
Molybdenum	ppm	<b>2</b>	<b>2</b>	 
Nickel	ppm	<b>■</b> 0	<1	 
Titanium	ppm	<1	<1	 
Silver	ppm	0	0	 
Manganese	ppm	<b>4</b>	<b>6</b>	 
Vanadium	ppm	0	<1	 
ADDITIV	FC			
Calcium	ppm	■17	<b>1</b> 1	 
Magnesium	ppm	<b>■</b> 6	<b>2</b>	 
Zinc	ppm	■6	■28	 
Phosphorus	ppm	<b>487</b>	<b>502</b>	 
Barium	ppm	<b>0</b>	<b>1</b>	 
Boron	ppm	<b>45</b>	0	 



ARNOLD MACHINERY COMPANY 4323 EAST WINSLOW AVENUE PHOENIX, AZ US 85040

Contact: RANDY PRZEKURAT randyp@arnoldmachinery.com T:

F: (602)414-1904

## Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. Gear wear is indicated. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO6174 **Unique No:** 10805880 Signed: Sean Felton Report Date: 28 Dec 2023



## **CONSTRUCTION EQUIPMENT**





