CONSTRUCTION EQUIPMENT SW0-068517 EPIROC D60-10 TMG23SED0506 - COOLANT

 Sample No:
 VCP447595

 Oil Type:
 NOT GIVEN

 Job No:
 SWO-068517

VOLVO

SAMPLE II	FORMATION				
Sample Number	-	VCP447595			
Sample Date		27 Dec 2023			
Machine Hours		263			
Sample Status		NORMAL			
COOLANT CONDITION					
рН	Scale 0-14	7.98			
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	676			
Percentage Glycol	%	45.4			
Freezing Point	°C	□ -24			
CONTAMINATION					
Coolant Appearance		normal			
Coolant Color		Pink			



WHITAKER CONTRACTING

692 CONVICT CAMP RD GUNTERSVILLE, AL US 35976 Contact: BROTHER WHITAKER BrotherWhitaker@whitaker-contracting.com T: (256)298-3905 F:

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. Glycol and nitrite levels are acceptable. The pH level of this fluid is within the acceptable limits.

 Depot:
 WHIGUN

 Unique No:
 10809939

 Signed:
 Jonathan Hester

 Report Date:
 04 Jan 2024

CONSTRUCTION EQUIPMENT



GRAPHS

Iron/Tin/Silver

VOLVO

