CONSTRUCTION EQUIPMENT SW0-068518 TAKEUCHI TL6 406002994 - COOLANT



Sample No:VCP428709Oil Type:VOLVO COOLANT VCS (YELLOW)

VOLVO

Job No:

Coolant Color

SWO-068518

SAMPLE INFORMATION

Sample Number	-	VCP428709	VCP380800		
Sample Date		27 Dec 2023	16 Jan 2023		
Machine Hours		1840	674		
Sample Status		NORMAL	NORMAL		
COOLANT	CONDITION				
рН	Scale 0-14	8.19	8.87		
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	NT	NT		
Percentage Glycol	%	47.0	46.4		
Freezing Point	°C	-28	-26		
CONTAMINATION					
Coolant Appearance		normal	normal		

Yllow

Yllow



WHITAKER CONTRACTING

692 CONVICT CAMP RD GUNTERSVILLE, AL US 35976 Contact: BROTHER WHITAKER BrotherWhitaker@whitaker-contracting.com T: (256)298-3905 F:

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:WHIGUNUnique No:10809944Signed:Jonathan HesterReport Date:04 Jan 2024


CONSTRUCTION EQUIPMENT



GRAPHS

Iron/Tin/Silver

VOLVO



Report Id: WHIGUN [WUSCAR] 06049336 (Generated: 01/04/2024 09:11:02) Rev: 1