

Sample No: VCP435640

Oil Type: VOLVO WB 101

Job No: SWO-068697

VOLVO	INFORMATION	d		
_	. INFURMATIUM			_
Sample Number		VCP435640		
Sample Date		04 Jan 2024		
Machine Hours		13655		
Oil Hours		0		
Oil Changed		Changed		
Sample Status		NORMAL		
OIL CON	DITION			
Visc @ 40°C	cSt	49.0		
		_		
VOLVO	UNATION			
LUNIAN	MINATION			
Water	%	NEG		
Silicon	ppm	19		
Sodium	ppm	0		
Potassium	ppm	2		
WEAR M	IETAI C			
_				
lron -	ppm	73		
Copper	ppm	■<1		
Lead	ppm			
Tin	ppm	■ <1		
Aluminum	ppm	■2		
Chromium	ppm	1		
Molybdenum	ppm	5		
Nickel	ppm			
Titanium	ppm	<1		
Silver	ppm	0		
Manganese	ppm	1		
Vanadium	ppm	0		
ADDITIV	IES			
Calcium	ppm	■3367		
Magnesium	ppm	57		
Zinc	ppm	■ 1333		
Phosphorus	ppm	1067		
Barium	ppm	7		
Boron	ppm	117		
DOTOIT	phili		_	



WHITAKER CONTRACTING

692 CONVICT CAMP RD GUNTERSVILLE, AL US 35976

Contact: BROTHER WHITAKER
BrotherWhitaker@whitaker-contracting.com
T: (256)298-3905
F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: WHIGUN
Unique No: 10820280
Signed: Wes Davis
Report Date: 09 Jan 2024



CONSTRUCTION EQUIPMENT





