CONSTRUCTION EQUIPMENT 634785 VOLVO A40G 752073 - TRANSMISSION (AUTO)



Sample No: VCP432200

VOLVO

Job No:

Boron

VOLVO

634785

SAMPLE INFORMATION						
			_		_	
Sample Number		VCP432200				
Sample Date		30 Nov 2023				RIPA AND ASSOCIATES
Machine Hours		527				10149 FISHER AVENUE
Oil Hours		527				TAMPA, FL
Oil Changed		Not Changd				US 33619
Sample Status		NORMAL				Contact: ROBERT TURNER
VOLVO						rturner@ripatampa.com
OIL CON	IDITION					T:
Visc @ 40°C	cSt	28.8				F:
	CST	20.0				
VOLVO						Diagnosis
	MINATION					Resample at the next service interval
Water	%	NEG				to monitor.All component wear rates
Silicon	ppm	10				are normal. There is no indication of
Sodium	ppm	0				any contamination in the fluid. The
Potassium	ppm	2				condition of the fluid is acceptable
						for the time in service.
WEAR I	METALS					
Iron	ppm	1 8				
Copper	ppm	16				
Lead	ppm	0				
Tin	ppm	1				
Aluminum	ppm	5				
Chromium	ppm					
Molybdenum	ppm	0				
Nickel	ppm	 <1				
Titanium	ppm	0				
Silver	ppm	0				
Manganese	ppm	2				
Vanadium	ppm	0				
	P.P.					
VOLVO						
ADDITI	VE2					
Calcium	ppm	74				
Magnesium	ppm	0				
Zinc	ppm	0				
Phosphorus	ppm	250				
Barium	ppm	3				

Depot:RIPTAMUnique No:10834613Signed:Don BaldridgeReport Date:19 Jan 2024

93

ppm

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO

