Sample No: VCP447958
Oil Type: {unknown}
Job No: W07014112

SAMPLE II	NFORMATION					
Sample Number	-	VCP447958				
Sample Date		10 Jan 2024				
Machine Hours		11633				
Oil Hours		0				
Oil Changed		Changed				
Sample Status		SEVERE				
OIL CONDITION						
Visc @ 40°C	cSt	<b>24.8</b>				

Visc @ 40°C	cSt	<b>24.8</b>				
TOLVO	IINATION					
CONTAMINATION						
Water	%	NEG				
Silicon	ppm	■21				
Sodium	ppm	<b>2</b>				
Potassium	ppm	<b>■</b> 3				
WEAR METALS						

WEAR I	METALS			
Iron	ppm	<b>1</b> 719	 	
Copper	ppm	<b>16</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	■0	 	
Aluminum	ppm	<b>6</b>	 	
Chromium	ppm	<b>5</b>	 	
Molybdenum	ppm	0	 	
Nickel	ppm	<b></b>	 	
Titanium	ppm	0	 	
Silver	ppm	■0	 	
Manganese	ppm	15	 	
Vanadium	ppm	0	 	

ADDITIVES						
Calcium	ppm	90				
Magnesium	ppm	1				
Zinc	ppm	0				
Phosphorus	ppm	225				
Barium	ppm	6				
Boron	ppm	44				



## **MORGAN LUMBER**

628 JEB STUART HWY RED OAK, VA US 23964

Contact: Service Manager

T: F:

## Diagnosis

Oil and filter change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. The iron level is severe. There is no indication of any contamination in the fluid. The fluid is no longer serviceable as a result of the abnormal and/or severe wear.

Depot:MORREDVAUnique No:10834616Signed:Don BaldridgeReport Date:19 Jan 2024



## **CONSTRUCTION EQUIPMENT**





