

# CONSTRUCTION EQUIPMENT VOLVO L120H 632841 - COOLANT



Sample No:VCP0008147Oil Type:{unknown}

### Job No:

| SAMPLE II          | NFORMATION |             |  |  |  |
|--------------------|------------|-------------|--|--|--|
| Sample Number      | -          | VCP0008147  |  |  |  |
| Sample Date        |            | 25 Jan 2024 |  |  |  |
| Machine Hours      |            | 8601        |  |  |  |
| Sample Status      |            | NORMAL      |  |  |  |
|                    |            |             |  |  |  |
| COOLANT CONDITION  |            |             |  |  |  |
| рН                 | Scale 0-14 | 7.67        |  |  |  |
| Reserve Alkalinity | Scale 0-20 |             |  |  |  |
| Nitrites           | ppm        | NT NT       |  |  |  |
| Percentage Glycol  | %          | 50.5        |  |  |  |
| Freezing Point     | °C         | 35          |  |  |  |
|                    |            |             |  |  |  |
| CONTAMINATION      |            |             |  |  |  |
| Coolant Appearance |            | normal      |  |  |  |
| Coolant Color      |            | Yllow       |  |  |  |



#### ALTA EQUIPMENT COMPANY

8750 PHILIPS HWY JACKSONVILLE, FL US 32256 Contact: TECHNICIAN ACCOUNT catherine.anastasio@wearcheck.com T: F: (904)737-1260

## Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

 Depot:
 VOLV00092

 Unique No:
 10858374

 Signed:
 Jonathan Hester

 Report Date:
 06 Feb 2024

Submitted By: TECHNICIAN ACCOUNT


# **CONSTRUCTION EQUIPMENT**



# GRAPHS

### Iron/Tin/Silver

VOLVO



Report Id: VOLVO0092 [WUSCAR] 06076283 (Generated: 02/08/2024 13:47:39) Rev: 1

Submitted By: TECHNICIAN ACCOUNT