

## CONSTRUCTION EQUIPMENT VOLVO EC480EL 314022 - RIGHT FINAL DRIVE



Sample No: VCP442691

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No:

VOLVO SAMPLE	INFORMATION				
Sample Number		VCP442691			
Sample Date		01 Feb 2024			
Machine Hours		2518			
		0			
Oil Changed					
Oil Changed		Changed			
Sample Status		SEVERE			
VOLVO					
OIL CONDITION					
Visc @ 40°C	cSt	<b>184</b>			
VOLVO					
VOLVO	INATION				
Water	%	■ 0.121			
Silicon	ppm	<b>1402</b>			
Sodium	ppm	<b>4</b>			
Potassium	ppm	<b>■</b> 7			
VOLVO					
WEAR M	FTALS				
Iron		<b>4474</b>			
Copper	ppm	<b>1474</b>			
Lead	ppm	<b>■</b> <1			
Tin	ppm	<b>0</b>			
Aluminum		<b>▲</b> 89			
Chromium	ppm	<b>3</b> 5			
Molybdenum	ppm	<b>4</b>			
Nickel	ppm	<u> </u>			
Titanium	ppm	10			
Silver	ppm	■0			
Manganese	ppm	■34			
Vanadium	ppm	<1			
Variation	ppiii	<b>\</b> 1			
VOLVO					
ADDITIV	F2				
Calcium	ppm	<b>653</b>			
Magnesium	ppm	<b>21</b>			
Zinc	ppm	<b>24</b>			
Phosphorus	ppm	■386			
Barium	ppm	<b>0</b>			
Boron	ppm	<b>6</b>			



## **ALTA EQUIPMENT COMPANY** 5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL

US 33905

Contact: TODD LARK tlark@altaequipfl.com

T:

F: (239)481-3302

## Diagnosis

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. Gear wear is indicated. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. The oil is no longer serviceable due to the presence of contaminants.

Depot:VOLVO0090Unique No:10862308Signed:Don BaldridgeReport Date:07 Feb 2024



## **CONSTRUCTION EQUIPMENT**





